# Baltimore's CSX Train Derailment: the AQI's role in Emergency Response

U.S. EPA National Air Quality Conference
February 6, 2002
Randy E. Mosier
Maryland Department of the Environment



### July 18, 2001

- CSX Train has brake actuation at around 3:10 PM
- First 9-1-1 calls at around 4:00 PM
- Train accident reported in the Howard Street Tunnel




### **Baltimore & Howard Street**





### Mt. Royal Station

- North End of Tunnel
- Initial Incident Command Post
- Residential and Commercial Area



### **Camden Yards**



- South End of Tunnel
- Main Incident Command Post


#### **Initial Priorities**

- Assess the train and contents
- Attack the fire
- Protect the community




#### The Train


- 3 locomotives, 60 freight cars
- Total length 4,001 feet
- Total weight 4,547 tons
- Mixed load: pulpboard, woodpulp, brick, soyoil, paper, plywood, steel
- 9 HAZMAT Cars








### **Getting to the Fire**




- First attempts at entry were on the north end
  - Too much heat, smoke and distance
- Dual attack from south end and manhole proved successful

### **Acid Transfer**



- Acid removal delayed by tunnel temperatures
- Vacuum truck pumps hydrochloric acid from damaged rail car
- Firefighters apply water spray for vapor suppression
- Small amount of acid leaked
  - Partially neutralized by limestone
  - Diluted by water main break and fire suppression

## Fighting Fire/Pumping Acid



### **Next Steps**



- Remove cars from both ends
- Extinguish burning cars
  - Fire burned for several days
- Secure HAZMAT cars

### Would you Believe...




### **City Impact**

- Major sections of downtown closed
- Orioles games rescheduled
- Businesses impacted
- Portions of Howard Street closed for 7
   weeks



### **City Impact**





## **Community Challenges**

- Smoke and soot concerns
- Airborne Toxics
- Inner Harbor Water Quality Concerns
- Heightened HAZMAT Awareness
- Lost Business
- Subsequent Event

### **Air Monitoring**

- Air monitored in tunnel vicinity, Howard Street and some nearby structures (residential, schools)
- Air monitored for CO, HCL vapor, total VOCs, combustible gases, pH
  - Continued long after the fire was out
- No indications of hazardous materials releases
- Joint federal, state, CSX effort

## Public Information Challenges

- Incorporation with existing AQI
- Use of Civil Defense Sirens
- Many voices, one message
- Effective spokespeople

### Thank you for your attention!



Randy E. Mosier

Maryland Department of the Environment

(410) 631-4488

rmosier@mde.state.md.us